



Playground Services Ltd

Quote QT-13266

November Operational Inspection Quote

Date:	25/11/2020
Client:	Saltwood Parish Council
Prepared for:	Louisa Johnson
Email Address:	
Prepared by:	Emma Gilham

SITE	SITE ITEM	DESCRIPTION	REMEDIAL ACTION	RISK ASSESSMENT	UNIT PRICE	QUANTITY	SUBTOTAL
Saltwood Play Area	2 Bays Mixed Swings Timber (2014)	The cradle seat is damaged.	Remove damaged cradle seat and replace with new cradle seat.	12	£239.00	1	£239.00
Saltwood Play Area	Cable Runway Timber (2014)	The chain cover is damaged.	Install new chain cover.	10	£77.25	1	£77.25
Saltwood Play Area	Cable Runway Timber (2014)	The top links and bolt are worn.	Remove worn links and replace with new.	10	£35.50	2	£71.00
Saltwood Play Area	Cable Runway Timber (2014)	There is a loose bolt (bottom of silver box frame on support posts)(take off point).	Tighten loose fixings.	10	£34.50	1	£34.50
Saltwood Play Area	Cable Runway Timber (2014)	There is a missing fixing. X3 nut and bolts on pulley system casing	Replace missing fixing.	12	£34.50	3	£34.50
Saltwood Play Area	Cable Runway Timber (2014)	There is a missing rubber cap on the spring buffer (x 2)(take off and finish point)(PLAYDALE).	Replace rubber cap.	10	£75.00	2	£150.00
Saltwood Play Area	Cable Runway Timber (2014)	There is an item missing from this unit. Brake system on pulley	Replace Item that is missing. Replace traveller.	10	£368.25	1	£368.25
Saltwood Play Area	Goal Mouth 1 (white)	There is a protruding fixing on the frame.	Cut off the protruding fixing where necessary.	10	£34.50	1	£34.50
Saltwood Play Area	Goal Mouth 2 (green)	Bottom silver support beams are damaged (1100 mm x 50 mm x 30 mm x 2).	Replace supports.	10	£195.00	2	£390.00
Saltwood Play Area	Goal Mouth 2 (green)	There is a missing donut cap on basket ball back board frame (x 4).	Install cap.	10	£35.50	4	£35.50
Saltwood Play Area	Goal Mouth 2 (green)	There is a missing plug on the frame (x 44).	Install cap.	10	£164.00	44	£164.00
Saltwood Play Area	Junior MPU Timber (2014)	There are loose fixings on the climbing net (x 2).	Tighten loose fixings.	10	£34.50	2	£34.50
Saltwood Play Area	Picnic Table Timber	The item is loose in the ground.	Re-secure item in the ground to prevent tipping over.	12	£135.00	1	£135.00
Saltwood Play Area	Picnic Table Timber	The timber seat is damaged.	Sand and seal damage.	10	£67.50	1	£67.50
Saltwood Play Area	Picnic Table Timber	There are protruding fixings (x 4).	Cut off the protruding fixing where necessary	10	£34.50	4	£34.50
Saltwood Play Area	Rotating Seats (2014)	The item requires lubricant. Between fixings around bearing	Item requires lubricant.	10	£67.50	1	£67.50
Saltwood Play Area	Rotating Seats (2014)	There is a missing cap on center post (playdale)	Install cap.	10	£35.50	1	£35.50
Saltwood Play Area	Roundabout	The bearing is worn.	Remove and investigate as the manufacturer is no longer trading.	10	£295.00	1	£295.00
Saltwood Play Area	Toddler MPU Timber (2014)	There is splits on the timber. Above climbing net.	Sand and seal split area.	10	£67.50	1	£67.50

SITE	SITE ITEM	DESCRIPTION	REMEDIAL ACTION	RISK ASSESSMENT	UNIT PRICE	QUANTITY	SUBTOTAL
Saltwood Play Area	Trim Trail Timber (2014)	The post on the swing steps is loose in the ground (x 2).	Re-secure item in the ground.Repair surface.	10	£295.00	2	£590.00
					SITE TOTAL		£2,925.50
					GRAND TOTAL		£2,925.50
					*ALL PRICES EXCLUSIVE OF VAT		E&OE